
## COYOTE® Dome Closure 9.5" x 28" with Transition Tray for High Density Splice Applications

Be sure to read and completely understand this procedure before applying product. Be sure to select the proper PREFORMED product before application.



#### **NOMENCLATURE**

- End Plate with HD Transition Tray Organizer (1)
- 2. Dome Cover (1)
- 3. Dome Gasket (1)
- 4. Dome Collar (1)
- 5. HD Closure Small Parts Bag (1)
- 6. 1 Hole Grommet Kit (0 or 1) (.60" – .85" Cable Range)
- 7. 1 Hole Grommet Kit (0 or 1) (.85" – 1.0" Cable Range)
- 8. 1 Hole Grommet Kit (0 or 2) (1.0" 1.25" Cable Range)

80813123

- 9. 1 Hole Grommet Kit (0 or 2) (1.25" – 1.38" Cable Range)
- 10. Small Parts Bag (1)
- 11. Transition Tube Kit (1)
- 12. Transport Tube Kit (1)
- 13. Spiral Wrap Tube Kit (1)
- 14. Ribbon Splice Tray Deep (Order Separately)
- 15. Single Fusion Splice Tray Thin (Order Separately)

#### **TOOLS REQUIRED**

- 3/8" & 7/16" Can wrench or socket wrench
- Side Cutters
- Snips

Single Fusion

(Double Stack)

Fiber optic cable opening tools

8

576

Density Splice Applications					
PLP Catalog Number	Description	Image	Splice Type	Max Trays per Closure	Closure Splice Capacity
80813121	Long Deep Profile Ribbon Flip Tray (288ct)		Mass Fusion/Ribbon	4	1,152

Long Thin Profile Single Fusion

Flip Tray (72ct)

PLP Catalog Number	Description				
	COYOTE® Dome Closure 9.5" x 28" Kits for High Density Splice Applications				
80061406	COYOTE Dome Closure 9.5" x 28" without Transition Tray for cables under 1.25" diameter. Includes (1) 1 Hole Grommet Kit - Cable Range .60"85" & (1) 1 Hole Grommet Kit - Cable Range .85"-1.0"				
80061407	COYOTE Dome Closure 9.5" x 28" with Transition Tray for cables under 1.25" diameter. Includes (1) 1 Hole Grommet Kit - Cable Range .60"85" & (1) 1 Hole Grommet Kit - Cable Range .85"-1.0"				
80061408	COYOTE Dome Closure 9.5" x 28" without Transition Tray for cables over 1.25" diameter. Includes (2) 1 Hole Grommet Kit - Cable Range 1.0"-1.25" & (2) 1 Hole Grommet Kit - Cable Range 1.25"-1.38"				
80061409	COYOTE Dome Closure 9.5" x 28" with Transition Tray for cables over 1.25" diameter. Includes (2) 1 Hole Grommet Kit - Cable Range 1.0"-1.25" & (2) 1 Hole Grommet Kit - Cable Range 1.25"-1.38"				
Accessory Kits for COYOTE Dome 9.5" x 28" Closures					
80807991	100ft. Roll of .25" ID Tubing				
80812618	Pack of (4) 18" Long Pieces of .25" ID Tubing				
80807571	6ft. Long Piece of .375" O.D. Spiral Wrap Tubing				
80805066-6	6ft. Long Piece of .625" O.D. Spiral Wrap Tubing				
80812881	100ft. Roll of .625" O.D. Spiral Wrap Tubing				
800015235	Replacement End Plate for the COYOTE Dome Closures 9.5" x 19" and 9.5" x 28"				
80812608	Closure O-Ring Sealing Gasket for the COYOTE Dome Closures 9.5" x 19" and 9.5" x 28"				
80808528-1	Latching Collar for the COYOTE Dome Closures 9.5" x 19" and 9.5" x 28"				
800015236	Strength Member Bracket Kit – Includes 3 Long L-Brackets and 3 Hose Clamps				
80808651	Strength Member Bracket Kit – Includes 4 Long L-Brackets				
80809205	Strength Member Bracket Kit – Includes 2 Short L-Brackets				
80813124	Splice Tray Locking Pin Kit. Includes (6) tray locking pins				
80813125	Splice Tray Tether Kit. Includes (6) Splice Tray Tether Straps				
80811036	6 Position Bobbin Kit for Retaining Drop Cables				
COYEPFIX1	COYOTE Dome End Plate Fixture				
	Mounting Brackets for COYOTE Dome 9.5" x 28" Closures				
8004037	Aerial Adjustable Offset Mounting Bracket (Dome Mount) - Strand Applications				
8004038	Aerial Adjustable Offset Mounting Bracket (Dome Mount) - ADSS Applications				
8003942	Pole/Wall Mounting Bracket				
8004003	Manhole Support				

COYOTE Grommet Chart for COYOTE Dome Closure 9.5" x 28" for High Density Splice Applications				
PLP Catalog Number	Cable Range Inches (mm)	Description	Image	Slitting Location
8003692	.60"85" (15 - 22 mm)	1-entry grommet		
8003693	.85" - 1.0" (22 - 25 mm)	1-entry grommet		
8003694	1.0" - 1.25" (25 - 32 mm)	1-entry grommet		
*8004145	1.25" - 1.38" (32 - 35 mm)	1-entry grommet		
8003663	.42"60" (11 - 15 mm)	2-entry grommet	00	69
8004065	.250"312" (6 - 8 mm)	4-entry grommet		
8003664	.30"43" (8 - 11 mm)	4-entry grommet		49
8003677	.125"25" (3 - 6 mm)	8-entry grommet	2433	N/A


#### **END PLATE PREPARATION**

Step #1 Determine which cable ports will be used and mark the respective breakout tabs of the end plate.



**NOTE:** For expressed buffer tube ribbon cables, use cable ports 3 and 6. Use all other cable ports for branch or drop cables if required


Step #2 Remove the end plate caps from the selected cable ports. Break out the outer and inner tabs of each cable port by snipping the grooves on both sides of each tab with side cutters. Once the grooves have been snipped, remove each tab by pulling the tab outwards from the end plate.





#### **CABLE PREPARATION**

**Step #3** Measure the cable to determine the diameter and hole location to use in the grommet.




Step #4 If using cut cable, insert the cable through the grommet. If your application requires express/balloon/ring cut cables, see Step 7 for the grommet slitting procedure.



### Step #5 Installing Figure 8 Style Cables and Cables with Tracer Wires

Remove tracer wire or ground wire from the portion of the cable that will be positioned in the grommet and insert cable into the grommet.








Correct Installation


Figure 8 Style Cable






orrect Installation Correct Installation


Step #6 Grommet Slitting – If slitting is required, lay the grommet on a stable flat surface. Position the utility knife with the cutting edge against the top surface and cut through the grommet. Consult the grommet chart on page 2 for slitting locations of all grommets.



**PLP Tip:** Use a pen to sketch slitting lines on top surface of grommet prior to cutting.




**Step #7** Prepare buffer tube ribbon cable(s) and unitube ribbon cable(s) for cut applications.



Minimum Sheath Opening for Cut Cable Applications		
80"	2.0 m	

PLP Tip: Leave about 8" (203 mm) of strength member to trim later.

**Step #8a** Prepare buffer tube ribbon cable(s) for mid sheath applications (Express/Balloon/Ring Cut).




**NOTE:** When expressing ribbons in the transition tray of the closure at this measurement, the maximum number of ribbons that can be expressed is 36 ribbons (432 fibers).

For Applications Where Fiber is Dedicated to the Splice Point			
Configuration	Cut Location	Sheath Opening	
Unitube/Ribbon Expressed (Mid-Sheath)	Α	Min of 80" (2.0 m)	

**PLP Tip:** Leave about 8" (203 mm) of strength member to trim later.

Step #8b Prepare buffer tube ribbon cable(s) for mid sheath applications (Express/Balloon/Ring Cut).




**NOTE:** When expressing ribbons in the transition tray of the closure at this measurement, the maximum number of ribbons that can be expressed is 36 ribbons (432 fibers).

For Applications Where Fiber is NOT Dedicated to the Splice Point			
Configuration	Cut Location	Sheath Opening	
Unitube/Ribbon Expressed (Mid-Sheath)	В	Min of 160" (4.1 m)	

**PLP Tip:** Leave about 8" (203 mm) of strength member to trim later.

Step #9 Align the sheath opening with the end of the slot of the strength member bracket as shown below and secure the cable to the bracket with the hose clamp provided.





**OPTIONAL - Securing Cable Strength Member to Strength Member Bracket** 

**Step #10** Assemble the adapter to the bracket as shown below.






Step #11 Trim the large strength member 1/2" (12.7 mm) past the end of the adapter. Secure the cable strength member to the adapter with the small hose clamp provided.




Step #12 Secure the cable to the strength member bracket with the hose clamp provided.




Step #13 Install a piece of spiral wrap tubing onto each buffer tube and slide it to the sheath opening of the cable.





**Step #14** Mark each buffer tube 17" (.43 m) away from the sheath opening and remove each buffer tube beyond the mark.





Step #15 Slide each piece of spiral wrap tubing over the ribbon fibers of the buffer tubes. Secure the spiral wrap tubing to each buffer tube with a piece of electrical tape as shown below.






#### Securing Cable Strength Member with Strength Member Bobbin (Only for use with Rollable/Spider Web Ribbon Cables)

Step #16 Trim the strength member 6" (152 mm) away from the sheath opening.

6" (152 mm)

Step #17 Install the bobbin on the end of the strength member as shown below.

Bobbin



#### Securing Branch/Drop Cable Strength Member(s) to Strength Member Bracket


Step #19 Prepare central buffer tube(s) for unitube/ribbon cable applications.


Cable in Entry
Ports 4 and 5

7" (178 mm)

Cable in Entry
Ports 1, 2, and 7

2.25" (57 mm)








Step #22 Install the cap on the strength member bracket and loosely secure it to the bracket with the small nut provided.

Cap

Small Nut









#### **Cable Installation and Routing**

**Step #26** Lubricate the sealing surface of the grommet with the silicone lubricant that is provided.



**Step #27** Position the grommets in the end plate slots.






Step #28 Position the slot of the strength member bracket leg over the stud and pull back the cable.



Step #29 Install the strength member bracket on the stud. Install the lock washer and nut against the bracket, but do not tighten fully, so that the bracket can slide as the grommet is compressed by the cable cap.



**Step #30** Install the cable caps and secure with hex bolts.



#### **NOTES:**

- Tighten bolts by hand evenly until cable cap is fully seated (DO NOT USE POWER TOOLS TO TIGHTEN BOLTS).
- When using a can wrench or nut driver, the installed torque is 35 to 40 in-lbs.
- •TIGHTEN ALL UNUSED CABLE CAPS.


IMPORTANT: Tighten down the strength member bracket after the caps are tightened.

Step #31 Complete end plate assembly shown below.




#### **ROUTING BUFFER TUBE RIBBON CABLE**

**Step #32** Route the buffer tubes through the side storage brackets.



Step #33


Secure the buffer tube(s) in the side storage brackets with the retainer clips. To install the retainer clip, position the bottom slot of the retainer clip onto the bottom portion of the side storage bracket. Tilt the retainer clip forward until the top portion of the side storage bracket snaps into the top slot of the retainer clip.






## ROUTING UNITUBE BRANCH/DROP RIBBON CABLE(S)


**Step #34** Route and secure the central tube of unitube cables to transition tray.




Step #35 Use transition tube(s) to route ribbons from unitube cables installed in the upper cable port(s) to the transition tray. Secure the transition tube(s) to the transition tray with tie wraps.




Step #36 Route feeder ribbons within the transition tray.



Step #37 Insert ribbons to be routed to the splice tray(s) into the transport tubes. Wrap a piece of felt around the ends of the transport tubes and secure the tubes to the transition tray with tie wraps.




Step #38 Install the transition tray cover on the transition tray by snapping the tabs of the cover into the slots of the transition tray.




#### **SPLICE TRAY INSTALLATION**

Step #39 Slide the hinge bracket of the splice tray into the slots of the spacer bracket until the hinge bracket is fully engaged into


the spacer bracket.





#### ROUTING SPIRAL WRAP TUBING TO THE SPLICE TRAYS

Step #40 Wrap the ends of each spiral wrap tube with a piece of felt and route the tubes to the splice trays. Secure the tubes to the splice trays with tie wraps.



**IMPORTANT NOTE:** If fibers are being expressed, route the spiral wrap tubes that contain the expressed fibers to the bottom splice tray. Use the remaining splice trays for storing spliced fibers.

#### **SPLICE TRAY MANAGEMENT**

Step #41 Route expressed fibers in the bottom splice tray as shown below.



Step #42 Route the first 12 incoming and outgoing ribbons in each splice tray as shown below.

Routing for Incoming Ribbons

Routing for Outgoing Ribbons

Step #43 Splice the first 12 incoming ribbons to first 12 outgoing ribbons per your accepted company practices.


**Splices** 


1-12

**Splices** 

1-12

Step #44 Install the platform into the splice tray by inserting the tab of the platform into the slot of the splice tray and then pushing the posts of the platform into the bosses of the splice tray





Step #45

Route the last 12 incoming and outgoing ribbons in each splice tray as shown below

Routing for Incoming Ribbons

Routing for Outgoing Ribbons

Step #46 Splice the last 12 incoming ribbons to last 12 outgoing ribbons per your accepted company practices.

**Splices** 

13-24

Splices

13-24

#### **SECURING SPLICE TRAYS**


Step #47

Determine the number of splice trays that are installed in the organizer and locate the corresponding number on the lock pin. Trim the lock pin at the notched location just below the number.


Notch


**Note:** One side of the lock pin is numbered 1-12 for thin profile splice trays and the other side of the lock pin is numbered 1-6 for deep profile splice trays.


Step #48 Install the lock pin into the hinge brackets as shown below.




Step #50 To secure the splice trays while they are flipped up, attach the tethers from the button tabs of the tether bracket to the button tabs of the bottom splice tray that is flipped up.







Step #51 When the tethers are not being used they can be stored on the tether bracket by securing the loose ends of the tethers to the middle button tab as shown below.




#### **Dome Preparation & Installation**


Step #52

Re-tighten all cable cap bolts (Step #30) to assure that the cable caps are fully seated. When using a can wrench or nut driver, the installed torque is 35 to 40 in-lbs.


Step #53 Lubricate all surfaces around gasket with silicone lubricant to assure easy assembly and closure re-entry.




**Step #54** Slide the end plate gasket onto the end plate and press into the groove.



Step #55 Work the gasket into the groove.



**Step #56** Position the dome over the end plate.



Step #57 Install the dome collar.





**Step #58** Fasten the latch and lock the collar by twisting the latch fastener clockwise 90 degrees.



#### **Flash Test Procedure**

**Step #59** Remove the cap from the air valve of the end plate.



**Step #60** Pressurize closure up to a max of 10psi.






Step #61 Spray all sealing surfaces of the dome end plate with a soap/water solution to determine if the end plate has been assembled properly.




Step #62 Release all pressure in the closure by pressing against the valve stem with the bump on the top of the air valve cap.






#### **Aerial Mounting Options**

# Step #63a For COYOTE® 9.5" Dome Strand Mount Aerial Offset Bracket Kit (PLP Cat.#: 8004037) and 9.5" Dome ADSS Mount Aerial Offset Bracket Kit (PLP Cat.#: 8004038). Assemble each bug nut or ADSS clamp to each top aerial offset bracket as shown below.





#### Step #63b

For Shorter Spacing. Align the top aerial offset bracket with the bottom aerial offset bracket in either Position 1 or Position 2 as shown below. Secure the top aerial offset bracket to the bottom aerial offset bracket with the bolts and keps nuts provided.





Position 1 – ADSS Clamp Shown





Position 2 – ADSS Clamp Shown

Step #63c For Taller Spacing. Align the top aerial offset bracket with the bottom aerial offset bracket in either Position 1 or Position 2 as shown below. Secure the top aerial offset bracket to the bottom aerial offset bracket with the bolts and keps nuts provided.






Position 1 - Strand Clamp Shown





Position 2 – Strand Clamp Shown

Step #64 Insert hose clamp through the slots in each of the bottom aerial offset brackets.



Step #65 Attach a second hose clamp to each hose clamp with the mounting bracket on it and tighten each pair of hose clamps around the dome in the banding slots.




Step #66 Bracket installed on the dome closure.

Strand Aerial Offset Bracket shown secured on a 9.5" Dome

#### **Pole/Wall Mounting Option**


Step #67 The COYOTE® 9.5" Dome Pole/Wall Mount Bracket (PLP Cat.#: 8003942).

Secure the gusset bracket to the hanger bracket with the bolts and nuts provided as shown below.




Step #68 The COYOTE 9.5" Dome Pole/ Wall Mount Bracket (PLP Cat. #: 8003942).

Attach the hanger bracket to the pole mounting plate with the gusset side facing the same side as the bolt hole tabs of the pole mounting bracket.




Step #69 The COYOTE 9.5" Dome Pole/ Wall Mount Bracket (PLP Cat. #: 8003942).

Install the pole/wall mount bracket assembly on to the grounding studs of the end plate of the closure and secure it to the end plate with the three nuts that are provided.



Step #70 Attach the dome pole mounting plate to a pole or a wall with either 5/8" through bolts, 1/4" lag screws, or banding.





#### SAFETY CONSIDERATIONS

This application procedure is not intended to supersede any company construction or safety standards. This procedure is offered only to illustrate safe application for the individual. **FAILURE TO FOLLOW THESE PROCEDURES MAY RESULT IN PERSONAL INJURY OR DEATH.** 

Do not modify this product under any circumstances.

This product is intended for use by trained technicians only. This product should not be used by anyone who is not familiar with, and not trained to use it.

When working in the area of energized lines, extra care should be taken to prevent accidental electrical contact.

For proper performance and personal safety, be sure to select the proper size PREFORMED™ product before application.

PREFORMED products are precision devices. To insure proper performance, they should be stored in cartons under cover and handled carefully.



## PREFORMED LINE PRODUCTS

P.O. Box 91129, Cleveland, Ohio 44101 • 440.461.5200 • preformed.com • e-mail: inquiries@preformed.com