

COYOTE® 3-Hole Silicone Grommet for COYOTE 9.5" Dome and COYOTE GLC Closures


Be sure to read and completely understand this procedure before applying product. Be sure to select the proper size PREFORMED™ product before application.

NOMENCLATURE


- 1. End Plate Grommet (1)
 - 1) 4.
- 2. Plugs (3)
- 5. Glove (1)

Measure Tape (1)

3. Silicone Lubricant (1)



Step #1	Measure cable to determine diameter and hole location to use in grommet.		
	COTORS TAPE EACH MARK - MARKS		




COYOTE Grommet Chart For use in COYOTE Domes 9.5" and GLC Closures				
PLP Catalog Number	Cable Range Inches (mm)	Description	Splitting Location	
8004141	.472"500" (12 - 12.7 mm)	3-entry grommet		

NOTE: Grommet Kit contains: (1) Grommet, (1) Set of Plugs, (1) Silicone Lubricant Pack, (1) Measure Tape, and (1) Glove

Step #3 Grommet Preparation

Select the entry hole(s) to be used in the grommet and pierce the thin layer of material covering the hole(s) on the outside surface.

Grommet Slitting Procedure for Express Cables - Lay grommet on a stable flat surface. Position utility knife with the cutting edge against the top surface and cut through grommet. Consult grommet chart at the top of this page for slitting locations of all grommets.



SAFETY CONSIDERATIONS

This application procedure is not intended to supersede any company construction or safety standards. This procedure is offered only to illustrate safe application for the individual. **FAILURE TO FOLLOW THESE PROCEDURES MAY RESULT IN PERSONAL INJURY OR DEATH.**

Do not modify this product under any circumstances.

This product is intended for use by trained technicians only. This product should not be used by anyone who is not familiar with, and not trained to use it.

When working in the area of energized lines, extra care should be taken to prevent accidental electrical contact.

For proper performance and personal safety, be sure to select the proper size PREFORMED™ product before application.

PREFORMED products are precision devices. To insure proper performance, they should be stored in cartons under cover and handled carefully.



P.O. Box 91129, Cleveland, Ohio 44101 • 440.461.5200 • www.preformed.com • e-mail: inquiries@preformed.com