
### Rodent Guard for COYOTE® Axcess Solutions™ Cabinets

Be sure to read and completely understand this procedure before applying product. Be sure to select the proper PREFORMED™ product before application.




RODENT GUARD KIT NOMENCLATURE


1. Grommet Port Adapter (2)

2. Rodent Guard Plates (4)


#### **Cable Port Removal**

Step #1 Remove the flat rubber grommet from the cable entrance port.







Step #2 Slide the rodent guard plate down into the cable port at an angle as shown below.




COYOTE Axcess Solutions™ Cabinets & Rodent Protection Kits		
Catalog #	Description	Product Code
WDC2A	Wall Mount Cabinet, Almond, up to 24 Fibers	7500351
WDC2B	Wall Mount Cabinet, Black, up to 24 Fibers	7500352
80812784B	Rodent Protection Kit for WDC2, quantity 1 per Cabinet (Max.# Port Adapters is 4)	80812784B
WDC4A	Wall Mount Cabinet, Almond, up to 48 Fibers	7500353
WDC4B	Wall Mount Cabinet, Black, up to 48 Fibers	7500354
80812784B	Rodent Protection Kit for WDC4, quantity 1 per Cabinet (Max.# Port Adapters is 4)	80812784B
WDC8A	Wall Mount Cabinet, Almond, up to 96 Fibers	7500355
WDC8B	Wall Mount Cabinet, Black, up to 96 Fibers	7500356
80812785B	Rodent Protection Kit for WDC8, quantity 1 per Cabinet (Max.# Port Adapters is 4)	80812785B
S10115102	Lock Set for Wall Mount Cabinets Inner Door with matching keys	S10115102
RDC2A	Rack Mount Cabinet,1RU, Almond, up to 12 Fibers	7500427
RDC2B	Rack Mount Cabinet, 11RU, Black, up to 12 Fibers	7500428
HOOLD	Rodent Protection Kit not available for RDC2	7000-20
RDC3A	Rack Mount Cabinet, 2RU, Almond, up to 36 Fibers	7500359
RDC3B	Rack Mount Cabinet, 2RU, Black, up to 36 Fibers	7500360
800014149B	Rodent Protection Kit for RDC3, quantity 1 per Cabinet (Max.# Port Adapters is 4)	800014149B
RDC6A	Rack Mount Cabinet, 2RU, Almond, up to 72 Fibers	7500361
RDC6B	Rack Mount Cabinet, 2RU, Black, up to 72 Fibers	7500360
800014149B	Rodent Protection Kit for RDC6, quantity 1 per Cabinet (Max.# Port Adapters is 4)	800014149B
RDC12A	Rack Mount Cabinet, 3RU, Almond, up to 144 Fibers	7500363
RDC12B	Rack Mount Cabinet, 3RU, Black, up to 144 Fibers	7500364
800014150B	Rodent Protection Kit for RDC12, quantity 1 per Cabinet (Max.# Port Adapters is 4)	800014150B
RDC12XA	Rack Mount Cabinet, 4RU, Almond, up to 144 Fibers	7500525
80812789B	Rodent Protection Kit for RDC12X, quantity 1 per Cabinet (Max.# Port Adapters is 4)	80812789B
RDC24A	Rack Mount Cabinet, 8RU, Almond, up to 288 Fibers	7500365
RDC24B	Rack Mount Cabinet, 8RU, Black, up to 288 Fibers	7500366
80812786B	Rodent Protection Kit for RDC24, quantity 1 per Cabinet (Max.# Port Adapters is 8)	80812786B
8003825	Port Adapter Kit, 1 Hole, .825 - 1.0"	8003825
8003826	Port Adapter Kit, 1 Hole, .60825"	8003826
8003827	Port Adapter Kit, 1 Hole, .4060"	8003827
8003828	Port Adapter Kit, 2 Hole, .27550"	8003828
8003812	Port Adapter Kit, 4 Hole, .12275"	8003812
8003818	Port Adapter Kit, 8 Hole, .1220"	8003818


**Step #3** Rotate the rodent guard plate to engage the tabs of the plate in the side of the cable port.






**Step #4** Insert a flat head screwdriver into the slot in rodent guard plate and bend to break out the knockout port.






#### **Grommet Adapter Port / Cable Installation**

Step #5 Install the rubber sealing washer on the grommet adapter port as shown below.




**Step #6** Insert the grommet adapter port into the cable port hole.



**Step #7** Place the thin plastic washer on the grommet adapter port on the inside of the cabinet.




**Step #8** Install the metal nut on the grommet adapter port to secure.




Step #9 Install the thick plastic washer and grommet on cable as shown below.


Push the cable through the washer and grommet so that roughly 8ft of cable has passed through the grommet.



**Step #10** Insert the cable through the grommet adapter port.




**Step #11** Remove the cable sheath.




X" = Minimum Sheath Opening for Cut Cable			
Rack Mount Cabinets	Min. of 90" (2.3 m)		
Wall Mount Cabinets (For 12 and 24 Fibers)	WDC2 = Min of 80" (2.0 m) WDC4 = Min of 100" (2.5m)		
Wall Mount Cabinets (Up to 96 Fibers)	Min of 90" (2.3 m)		
Wall Mount Cabinets (Up to 144 Fibers)	Min of 110" (2.8 m)		

**PLP Tip:** Leave about 8" (203 mm) of strength member to trim later.


**Step #12** Trim strength member of cable as shown below.




Step #13 Position the strength member of the cable under the cap of the strength member bracket and tighten the nut to secure the strength member.




**Step #15** Slide the grommet and the plastic washer over the cable and insert the grommet into the grommet adapter port.




Step #14 Secure the strength member bracket to the cabinet with the bolt, lock washer, and nut as shown below.







**Step #16** Slide the adapter port nut halves apart as shown below.



**Step #17** Position the adapter port nut halves around the cable and slide the halves together.





**Step #18** Install the adapter port nut on the grommet adapter port to secure the cable.



#### SAFETY CONSIDERATIONS

This application procedure is not intended to supersede any company construction or safety standards. This procedure is offered only to illustrate safe application for the individual.

## FAILURE TO FOLLOW THESE PROCEDURES MAY RESULT IN PERSONAL INJURY OR DEATH. Do not modify this product under any circumstances.

This product is intended for use by trained technicians only. This product should not be used by anyone who is not familiar with, and not trained to use it.

When working in the area of energized lines, extra care should be taken to prevent accidental electrical contact.

For proper performance and personal safety, be sure to select the proper size PREFORMED $^{\text{TM}}$  product before application.

PREFORMED products are precision devices. To insure proper performance, they should be stored in cartons under cover and handled carefully.



# PREFORMED LINE PRODUCTS

P.O. Box 91129, Cleveland, Ohio 44101 • 440.461.5200 • www.preformed.com • e-mail: inquiries@preformed.com **SP3394**